#### U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT Azzo - Removal Polrep Initial and Final Removal Polrep

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region V

Subject: POLREP #1 Initial / Final

Azzo

Detroit, MI

Latitude: 42.4147990 Longitude: -83.2780075

To: Jason El-Zein, U.S. EPA

Matt Mankowski, U.S. EPA Sam Borries, U.S. EPA Mark Durno, U.S. EPA Carolyn Bohlen, U.S. EPA

Yolanda Bouchee-Cureton, U.S. EPA

HQ EOC, U.S. EPA John Maritote, U.S. EPA Carol Ropski, U.S. EPA Brian Schlieger, U.S. EPA

Ray Scott. Detroit Environmental Affairs

USCG PolRep Distribution, USCG

Lindy Nelson, U.S. DOI Jennifer Wolf, MDEQ Joe Walczak, MDEQ Bruce VanOtteren, MDEQ

Brian Kelly, OSC From: 7/20/2015 Date:

**Reporting Period:** 

### 1. Introduction

1.1 Background

Site Number: C56Y **Contract Number:** D.O. Number: **Action Memo Date:** 

Response Authority: CERCLA Response Type: Emergency Response Lead: PRP Incident Category: Removal Action

**NPL Status:** Non NPL **Operable Unit:** 

**Mobilization Date: Start Date:** 4/17/2015 **Demob Date:** Completion Date: 7/20/2015

CERCLIS ID: MIN000505825 **RCRIS ID:** ERNS No.: State Notification: FPN#: Reimbursable Account #:

# **Incident Category**

PRP CERCLA Emergency Response

### Site Description and Location

The Azzo site is an abandoned auto repair shop located at 24052 W. McNichols Avenue, Detroit, Michigan 48219 and is approximately one half of an acre in size. The site is located in an area of Detroit that is characterized by residential and commercial development. An Environmental Justice analysis for the site indicated there was a high potential for EJ concerns.

### **Description of Threat**

The site was discovered by the Detroit Fire Marshall's office who documented 40 containers of waste. An EPA site visit found evidence that the contents in the drums and small containers included ignitable and corrosive hazardous wastes, as defined by 40 C.F.R. § 261.21 (characteristic of ignitability) and 40 C.F.R. § 261.22 (characteristic of corrosivity), which are considered hazardous substances under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). These hazardous wastes were abandoned, unsecured, and a potential threat to human health and the environment.

# 2. Current Activities

# 2.1 Operations Section

### Narrative

EPA located the owner of the facility, who agreed to remove the wastes and secure the building. On July 10, EPA reassessed the facility; the 55 gallon drums and the majority of small containers had been removed, the entrances to the building had been secured, and the owner was in the process of having power restored and an alarm system installed. The owner stated the three remaining 5-gallon containers were to be used in the new business. As they were unused, and the building was now secured, no further action was taken.

## Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

AMN Investments LLC

Estimated Cost: \$3,500

### **Progress Metrics**

### **Regional Metrics**

Miles of river systems cleaned and/or restored **Cubic yards of contaminated sediments** n This is an Integrated River Assessment. The removed and/or capped numbers should overlap. Gallons of oil/water recovered Acres of soil/sediment cleaned up in floodplains and riverbanks Number of contaminated residential yards cleaned up **Stand Alone Assessment** Number of workers on site 2 Contaminant(s) of Concern Flammable and Corrosive

Oil Response Tracking

**CANAPS** Info

Initial amount released **Estimated volume** 

Final amount collected N/A **FPN Ceiling Amount** N/A **FPN Number** N/A **Body of Water affected** N/A

Community challenges or high involvement

N/A

Radiological

Residential impacts

**Explosives** 

Administrative and Logistical Factors (Place X where applicable)

Precedent-Setting HQ Consultations (e.g.,

fracking, asbestos)

**Endangered Species Act / Essential Fish** More than one PRP

Habitat issues

AOC Historic preservation issues

UAO **NPL** site Relocation

DOJ involved Remote location **Drinking water impacted** 

**Criminal Investigation Division involved** Extreme weather or abnormal field season X **Environmental justice** 

Tribal consultation or coordination or other Congressional involvement High media interest issues

Statutory Exemption for \$2 Million Statutory Exemption for 1 Year Active fire present

Hazmat Entry Conducted - Level A, B or C Incident or Unified Command established Actual air release (not threatened)

Waste Stream	Medium	Quantity	Disposal
Flammable	Liquids	100 gallons	
Chorrosive	Liquid	50 gallons	
Debris	Solid	20 cubic yards	

# 2.2 Planning Section

## **Anticipated Activities**

None - site closed

## 2.3 Logistics Section

No information available at this time.

## 2.4 Finance Section

No information available at this time.

## 2.5 Other Command Staff

No information available at this time.

# 3. Participating Entities

No information available at this time.

### 4. Personnel On Site

No information available at this time.

# 5. Definition of Terms

No information available at this time.

### 6. Additional sources of information

No information available at this time.

# 7. Situational Reference Materials

No information available at this time